ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
3

Ward Name
Atturu

Street ID
W0813, W0466, W0819, W0807, W0825, W0829

Street Name
NA, 1st Main Rd

Significant Landmark
BHEL Layout and Escort Layout

Segment No.
3/S-W0813/S030404

Total Length (m)
30.29

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	7.08	77.547708	13.093385	77.547772	13.093374	W0466	W0829
2	6.50	77.547370	13.093429	77.547429	13.093419	W0466	W0825
3	6.75	77.547048	13.093476	77.547110	13.093468	W0466	W0819
4	6.14	77.546721	13.093533	77.546777	13.093528	W0466	W0813
5	3.82	77.546391	13.093573	77.546426	13.093567	W0466	W0807

Work Details

History of Road / Lane / Circles

Name of the Work
Construction of culvert along main and cross roads of BHEL Layout and Escort Layout in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
1000000

Sanctioned Year
2017

Year
2017 - 2018

Type of Work
Others

Other Work Type
culvert along main and cross roads

Tender
Tender

Work Details
Construction of culvert along main and cross roads of BHEL Layout and Escort Layout in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone

Job No. / Work Code
003-17-000035

Work Order No.
EE (YNK.D)E-PMT-07/WO/14/2017-18

Work Order Date
27/04/2017

Period of Extention
90 DAYS

Defect Liability Period From
30/06/2017

Defect Liability Period To
29/06/2018

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Contractor Reg No (BBMP/PWD)

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0813, W0466, W0819, W0807,

Name of Contractor		Expenditure Booked \ Released (Rs)
K R TARANATH		948756.67
Phone No.	E-Mail ID	
9611343023		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		CHANDRAKANTH
Date of Inspection	**Remarks**	
12/07/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	12/07/2017	11/08/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Atturu **Street ID:** W0813, W0466, W0819, W0807,

	VASU K M	12/07/2017	11/08/2017	COMPLETED
EE	VASU K M	12/07/2017	11/08/2017	COMPLETED
AEE	ASHOK	12/07/2017	11/08/2017	COMPLETED
AE	CHANDRAKANTH	12/07/2017	11/08/2017	COMPLETED
AE	CHANDRAKANTH	12/07/2017	11/08/2017	COMPLETED

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W0813, W0466, W0819, W0807,